KENNECOTT TIMELINESeptember, 2015 – Lead Paint Mitigation and Asbestos Abatement

	Building	Year Purchased	Year Full Treatment	Mitigation or Abatement
			Completed	
1	Recreation Hall	1998	2003	Painted interior and exterior
2	Kennecott Cottage – #32-13	2002	2008	Painted interior and exterior
3	Kennecott Cottage – #32-19	2002	2008	Painted interior and exterior
4	Refrigeration Plant	1998	2006	Painted interior and exterior
5	General Manager's Office	1998	2008	Painted interior and exterior
6	Company Store & Warehouse – Phase I	1998	2006	Painted interior and exterior
7	Old School	2001	2003	Painted interior and exterior
8	Depot	1998	2002	Painted interior and exterior
9	Trestle Reconstruction	1998	2007	Asbestos abatement of exposed pipes
10	Dairy Barn	2004	2010	Painted interior and exterior
11	Assay Building Demolition	1998	2007	Asbestos abatement of exposed pipes
12	East Bunkhouse - Stabilization	2005	2016	Painted exterior
13	Machine Shop	1998	2012	Painted exterior
14	Power Plant	1998	2014	Painted exterior and sealed boilers
15	Leaching Plant – North Sacking Shed Stabilization	1998	2012	Painted exterior
16	Leaching Plant – South Sacking Shed Stabilization	1998	2013	Painted exterior
17	Kennecott Cottage – 32-8	2003	2013	Painted interior and exterior
18	West Bunkhouse - Exterior	1998	2014	Painted exterior
19	New School	1998	2004	Painted interior and exterior
20	Asbestos Abatement Erie	1998	2005	Abatement of asbestos on boiler and pipes
21	Asbestos Abatement Transformer House and Utilidors and General Manager's Office	1998	2004	Asbestos abatement of exposed pipes
22	Power Plant Bunker C Clean Up	1998	2010	Removed bunker C from pipes throughout building
23	Fire Hose House #3 Stabilization	1998	2005	Painted exterior
24	Stabilize National Creek Footbridge	1998	2003	Replaced and painted deck and railings
25	Remediate Hydrocarbons at Power Plant	1998	2004	Remove contaminated soils from foundation footing on south side of Power Plant

26	Blasting Cap Mitigation at Mill and Leaching Plant Sites	1998	2013	Constructed fences around known disposal sites and placed signage